

2008 Bowyers Stream River Control Works



This pool had its right bank removed, previously it extended most of the length of the pool and the work removed any cover for fish...



Same treatment on another pool

2008 Bowyers Stream River Control Works



And another – in fact this pool was completely removed and turned into the channel we now see



More channelling

2008 Bowyers Stream River Control Works



Once a nice pool...



Closer up of the same pool showing how gravel has been pushed in

2008 Bowyers Stream River Control Works



Another pool filled in against the bank removing cover



Blade down whilst driving up the river

2008 Bowyers Stream River Control Works



Dirty Water and dozer track